

EXECUTIVE SUMMARY

This report presents a summary of performance of operation, maintenance, and monitoring activities conducted at OU 7 Building 225 Floor Slab over the last year. These activities were performed as specified in the *Inspection, Operation, and Maintenance Plan (IOMP) for Hill AFB CERCLA Cap System* (Montgomery Watson, 1999).

There were no serious defects or issues identified during the annual Building 225 Floor Slab inspection. All data has been loaded into the Microsoft Access CERCLA Cap System Database.

Planned activity for next year consists of continued compliance with the IOMP.