

**TABLE 2-2**  
**NFRAP IRP SITE SUMMARY**  
(1 of 3)

IRP Site Code	Site Description	Material Stored/ Released	Dates of Operation	Regulatory Mechanism	Status	Location	Decision Document	Programmed Remedial Action	Site Closed
LF012	Landfill 2	Solid Wastes	1963–1965	CERCLA	NFRAP	Hill	1994	NFRAP	1994
OT014	Golf Course	Unknown	1960–Present	CERCLA	NFRAP	Hill	1991	NFRAP	1991
OT020	Spoils Pit	Construction debris	1972–1989	CERCLA	NFRAP	Hill	1992	NFRAP	1992
OT029	Building 204	Beryllium	Unknown	CERCLA	NFRAP	Hill	1998	NFRAP	2001
OT041	Northgate Dump	Debris	1963–1965	CERCLA	NFRAP	Hill	1994	NFRAP	1994
OT042	Munitions Dump	Debris	1942–1948	CERCLA	NFRAP	Hill	1994	NFRAP	1994
SD023	Pond 3	Stormwater	1957–Present	CERCLA	NFRAP	Hill	1995	NFRAP	1995
SD034	Pond 1	Stormwater	1940s–Present	CERCLA	NFRAP	Hill	1995	NFRAP	1995
SD040	Pond 6 (Pond 7)	Stormwater	1976–Present	CERCLA	NFRAP	Hill	1998	NFRAP	Re-opened
SD046	Storm Pond 2	Stormwater	1942–1974	CERCLA	NFRAP	Hill	1992	NFRAP	1992
SS021	Perimeter Road	Waste Solvents	1940s–1979	CERCLA	NFRAP	Hill	1991	NFRAP	1991
SS028	Sill Property	Chromium	1989	CERCLA	NFRAP	Layton	1991	NFRAP	1991
SS030	Bldg 20 (PCB)	PCBs	Unknown	TSCA	NFRAP	Hill	1992	NFRAP	1992
SS032	Bldg 225 (PCB)	PCBs	1940s–Present	CERCLA	NFRAP	Hill	1995	NFRAP	1995
ST018	Bldg 511, 514	Waste Solvents, Fuel	1950s–1985	CERCLA	NFRAP	Hill	1999	NFRAP	2001
ST031	Bldg 220	Wastewater	1940s–Present	CERCLA	NFRAP	Hill	1995	NFRAP	1998
ST035	Bldg 280 (UST)	JP-4	1941–Active	UST	NFRAP	Hill	1995	NFRAP	1998
ST036	Bldg 510 (UST)	Stoddard solvent	1953–1989	UST	NFRAP	Hill	1993	NFRAP	1996
ST037	Bldg 214 (UST)	Stoddard solvent	1964–1989	UST	NFRAP	Hill	1993	NFRAP	1996
ST038	Bldg 1141 (UST)	Diesel	Unknown–1989	UST	NFRAP	Hill	1991	NFRAP	1998
ST039	Bldg 1230 (UST)	Diesel	Unknown–1990	UST	NFRAP	Hill	1992	NFRAP	1995
ST043	Bldg 460 (UST)	Diesel, fuel oil	1959–1989	UST	NFRAP	Hill	1992	NFRAP	1995
ST044	Bldg 598 (UST)	Diesel	Unknown–1990	UST	NFRAP	Hill	1992	NFRAP	1995
ST045	Bldg 1214 (UST)	Diesel	Unknown–1990	UST	NFRAP	Hill	1992	NFRAP	1992
ST047	Bldg 26 (UST)	Gasoline	1942–1988	UST	NFRAP	Hill	1994	NFRAP	1995
ST048	Bldg 32 (UST)	Diesel, gasoline	1941–1988	UST	NFRAP	Hill	1993	NFRAP	1998
ST049	Bldg 41 (UST)	Fuel Oil (heating)	1965–1987	GWP	NFRAP	Hill	1993	NFRAP	1997

**TABLE 2-2**  
**NFRAP IRP SITE SUMMARY**  
**(2 of 3)**

IRP Site Code	Site Description	Material Stored/ Released	Dates of Operation	Regulatory Mechanism	Status	Location	Decision Document	Programmed Remedial Action	Site Closed
ST049	Bldg 41 (UST)	Fuel Oil (heating)	1968–1987	GWP	NFRAP	Hill	1994	NFRAP	1997
ST050	Bldg 204 (UST)	Diesel	1942–1987	UST	NFRAP	Hill	1993	NFRAP	1996
ST051	Bldg 221 (UST)	Diesel	Unknown–1990	UST	NFRAP	Hill	1992	NFRAP	1992
ST052	Bldg 242 (UST)	Fuel Oil (heating)	Unknown–1987	GWP	NFRAP	Hill	1996	NFRAP	1996
ST053	Bldg 256 (UST)	Fuel Oil (heating)	Unknown–1987	GWP	NFRAP	Hill	1996	NFRAP	1996
ST054	Bldg 308 (UST)	Fuel Oil (heating)	1942–1988	GWP	NFRAP	Hill	1993	NFRAP	1993
ST055	Bldg 388 (UST)	JP-4	Unknown–1987	UST	NFRAP	Hill	1994	NFRAP	1996
ST056	Bldg 924 (UST)	Diesel, gasoline	1969–1992	UST	NFRAP	Hill	1993	NFRAP	1996
ST057	Bldg 1243 (UST)	Diesel, gasoline	1960–1988	GWP	NFRAP	Hill	1994	NFRAP	1994
ST059	Bldg 5026 (UST)	Diesel, gasoline, Stoddard solvents	1969–1992	UST	NFRAP	Hill	1993	NFRAP	1995
ST060	Bldg 592 (UST)	Diesel, gasoline, JP-4	1986–Active	UST	NFRAP	Hill	1993	NFRAP	1995
ST062	Bldg 1102 (UST)	Diesel	Unknown–Active	UST	NFRAP	Hill	1992	NFRAP	1995
ST063	Bldg 837 (UST)	Diesel	198–1992	UST	NFRAP	Hill	1992	NFRAP	1995
ST064	Bldg 228 (UST)	JP-4	1970–Active	UST	NFRAP	Hill	1993	NFRAP	1996
ST065	Bldg 236 (UST)	Purge fluid, slop tank (JP-4/water)	1983–Active	UST	NFRAP	Hill	1995	NFRAP	1995
ST066	Bldg 4301 (UST)	Gasoline	1954–1991	UST	NFRAP	LMTA	1993	NFRAP	1998
ST067	Bldg 1705 (UST)	Diesel, gasoline	1980–1992	UST	NFRAP	Hill	1993	NFRAP	1996
ST068	Bldg 10779 (UST)	Slop tank (JP-4/water)	1973–1992	UST	NFRAP	Hill	1995	NFRAP	1997
ST069	Bldg 722 (UST)	Gasoline	1972–1992	UST	NFRAP	Hill	1993	NFRAP	1993
ST070	Bldg 1132 (UST)	Diesel	1976–1992	UST	NFRAP	Hill	1993	NFRAP	1993
ST072	Bldg 1590 (UST)	Fuel Oil (heating)	1964–Active	GWP	Hold	Hill	ND	NFRAP	1994
ST074	Bldg 260 (UST)	JP-4/Fuel Oil (heating)	1958–Active	UST	RA/LTM	Hill	1996	LTM. NFRAP	1998
ST075	Bldg 555 (UST)	Fuel Oil (heating)	Unknown–1993	GWP	NFRAP	Hill	1994	NFRAP	1994
ST076	Bldg 553 (UST)	Fuel Oil (heating)	Unknown–1994	GWP	NFRAP	Hill	1994	NFRAP	1994
ST077	Bldg 780 (UST)	Diesel	1965–1994	UST	NFRAP	Hill	1995	NFRAP	1995

**TABLE 2-2**  
**NFRAP IRP SITE SUMMARY**  
(3 of 3)

IRP Site Code	Site Description	Material Stored/ Released	Dates of Operation	Regulatory Mechanism	Status	Location	Decision Document	Programmed Remedial Action	Site Closed
ST078	Bldg 744 (UST)	Fuel Oil (heating)	Unknown–Active	GWP	Hold	Hill	1994	NFRAP at this time. Currently in use	1993
ST079	Bldg 40002 (UST)	Diesel, gasoline	1975–1992	UST	RA/LTM	UTTR	1994	NFRAP	2001
ST081	Fire Training Area 2	JP-4; other fuels	1973–1995	CERCLA	NFRAP	Hill	1998	NFRAP	2001
ST082	Bldg 1 (UST)	Diesel	1982–1991	UST	NFRAP	Hill	1993	NFRAP	1996
ST083	Bldg 771 (UST)	Fuel Oil (heating)	1975–1992	UST	NFRAP	Hill	1994	NFRAP	1996
ST084	Bldg 859 (UST)	Pesticides/Herbicides	1983–1993	UST	NFRAP	Hill	1994	NFRAP	1994
ST085	Bldgs 1313, 1314 (UST)	Diesel	1941–Active	GWP	RA/LTM	Hill	1996	LTM of bioventing system	2000
ST086	Bldgs 1134, 454, (UST) 1703, 1904, 2025,2104, 2203, 825	Fuel Oil, diesel, gasoline, waste oil	1957–Active	GWP/UST	NFRAP/RA/LTM	Hill	1995 1998	NFRAP	1998 (454, 1703)
ST087	Little Mtn Tank Farm	Jet fuel, Stoddard solvents, diesel, fuel oil	1958–Active	GWP	NFRAP	LMTA	Pending	NFRAP	1999
ST088	Little Mountain Fire Training Area (UST)	JP-4, Diesel	1970–1973	GWP	NFRAP	LMTA	1997	NFRAP	1997
ST097	Building 454	Waste Oil	1966–Present	UST	NFRAP	Hill	1997	NFRAP	1998
WP006	IWTP Sludge Drying Beds	Industrial Sludge	1956–1982	CERCLA	NFRAP	Hill	1995	NFRAP	1995
OT013	Agent Orange Test Area–UTTR	Herbicides	1972–1973	RCRA	NFRAP	Hill	1990	NFRAP	1990
SD016	Bamberger Pond	Stormwater	1950s–Active	CERCLA	NFRAP	Hill	2000	NFRAP	2000

(a) Interim action underway

(b) Based on relative risk

(c) Corrective actions are either complete or in progress for these sites. In many cases, EMR submitted CAPs and completed proposed actions prior to official acceptance by UDERR. This approach has been accepted by UDERR.

AST	Aboveground Storage Tank	NA	Not Applicable	TSCA	Toxic Substance Control Act
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act	ND	No Document	UDERR	Utah Department of Environmental Quality/Division of Environmental Response and Remediation
DD	Decision Document	NFRAP	No Further Response Action Planned		
GWP	Utah Ground Water Protection Program	NP	Not Prioritized	Unkn	Unknown
Layton	Layton City, Utah	RA	Remedial Action	UST	Underground Storage Tank
LMTA	Little Mountain Test Annex	RCRA	Resource Conservation and Recovery Act	UTTR	Utah Test and Training Range